

# Firmware Release Notes

## Version 4.0r1

### Overview of ISP / I.ISP firmware installation

The ISP / I.ISP Firmware is a complete firmware package compatible with all products of the StormAudio Immersive and Integrated Immersive Sound Processor range, being from the MK1 or MK2 families. Although the firmware package is common, the hardware platforms have differences leading to different features available and therefore different possible known issues.

This Release Notes document summarizes the firmware status for both MK1 and MK2 units, including all so far known issues and limitations. For a detailed information about the whole firmware upgrade process, please consult “StormAudio - Firmware Upgrade - Quick Guide - 2020.03.pdf” file that you can download from the Client Portal (<http://www.stormaudio.com>) using your login and password information. Please contact your distributor to obtain access information or email [info@stormaudio.com](mailto:info@stormaudio.com).

### Download information

The upgrade package can be downloaded from the StormAudio Support webpage of the Client Portal indicated above. File name will be: **isp\_4.0r2\_20200610.ssp** with an approximate size of 77 MB.

### Upgrade information

Make sure to first do a backup of the configuration of your ISP / I.ISP. Check updated Installer Guide or Owner Manual for more information on Backup Configuration feature.

If upgrading from an earlier version than V4.0r0 firmware such as 3.5rx, please follow below steps prior to upgrading to V4.0r2.

#### Important recommendations:

- Start first with an upgrade to 3.5r7 firmware to ensure product configuration and database is up to date (make a configuration backup first)
- For multiway speakers, use the “Dirac setup” to **group channels into speaker**
- **Ungroup** subwoofers and other speakers
- Upgrade to 4.0r0



Ch.	Signal	Channel Name	Speaker Group
1	LF	Left Front High	1
2	LF	Left Front Low	1
3	CF	Center Front High	3
4	CF	Center Front Low	3
5	RF	Right Front High	5
6	RF	Right Front Low	5
7	SUB	Main Sub / LFE Channel	7
8	LS	Left Surround	8
9	RS	Right Surround	9
10	LFT	Left Front Top	10
11	RFT	Right Front Top	11
12	LBT	Left Back Top	12
13	RBT	Right Back Top	13

Upgrade from Firmware earlier than 2.1r0 requires specific actions.

**Please contact our support team for further information** ([support@stormaudio.com](mailto:support@stormaudio.com)).

Upgrading from 2.1r2, make sure the date is part of the file name, such as **isp\_4.0r2\_20200610.ssp**. If not add it.

Upgrade from 2.1r2 onward can be done using described process.

The upgrade can be done either via the Web User Interface Remote Upgrade function (by entering the Unit IP on a web browser and selecting the System tab) or via a USB dongle key connected in the back panel of the unit. We recommend the use of the Web User Interface.

## Upgrade process

The upgrade process can be monitored either on the Web User Interface (banner on top of the page, green at the beginning and red during the upgrade) or on the Front Panel display. A step by step process will be shown.

Do not interrupt the process before reading the message:

“Update finished successfully; unit will restart shortly”.

Unit will restart automatically when upgrade is done through the Web User Interface.

## Internal software versions overview.

Following the upgrade of the ISP/I.ISP, you can verify that the system has been properly updated by checking each internal module versions. Click on “V4.0r2” firmware version indication in the System page of the Web User Interface and the below pop-up window will be shown.

MK1

FIRMWARE	4.0r2
MODEL	ISP Elite
SERIAL NUMBER	
HOSTNAME	
<b>SOFTWARE</b>	
BUILD DATE	Jun 10 2020
LINUX	4.4.8
OS	916 (7c3808f)
PROCESSOR SOFTWARE	v3627 (67a9d2c)
WEB UI	v2 (e347269)
DATABASE	19
MAIN FIRMWARE	119.9
MAIN BOOTLOADER	0x00000002
FRONT PANEL FIRMWARE	v11.15
COPROCESSOR A	0x00000212
COPROCESSOR B	0x00000025
COPROCESSOR C	0x00000026
COPROCESSOR D	0x00000026
FPGA A	0x00000013
FPGA B	0x00000014
DECODER	v2.2.6 8909 Oct 22 2018
HDMI FIRMWARE	v1.20

MK2

FIRMWARE	4.0r2
MODEL	ISP MK2
SERIAL NUMBER	
HOSTNAME	
<b>SOFTWARE</b>	
BUILD DATE	Jun 10 2020
LINUX	4.4.8
OS	916 (7c3808f)
PROCESSOR SOFTWARE	v3627 (67a9d2c)
WEB UI	v2 (e347269)
DATABASE	19
MAIN FIRMWARE	119.9
MAIN BOOTLOADER	0x00000005
FRONT PANEL FIRMWARE	v11.15
COPROCESSOR A	0x00000212
COPROCESSOR B	0x00000025
COPROCESSOR C	0x00000026
COPROCESSOR D	0x00000026
FPGA A	0x00000013
FPGA B	0x00000014
DECODER	APM 117 v101, Apr 6 2020
HDMI FIRMWARE	v1.20

## Changes from 4.0r1 to 4.0r2

### Common to all ISP/I.ISP

- Fix single tab issue in Safari on mac OS Catalina ([WebKit Bugzilla](#)). It is recommended to remove cache for all IP related to StormAudio devices (<https://support.apple.com/fr-fr/guide/safari/sfri47acf5d6/mac>).

- Fix word spelling in EQs page.
- Fix word spelling in contextual help.
- Fix issue where it was not possible to wake-up device from Deep Standby state.

## Features not present in this release

- DTS:X Pro decoder not yet activated (MK2 & MK1.5).
- IMAX Enhanced decoder is not yet activated (MK2 & MK1.5).
- Zone2 audio in path for HDMI / AES aux.
- ROON application cannot control ZONES
- HMC-82 HDMI board, CEC command.
- New multi bass zones Expert Bass Management not yet activated.

## Known bugs, issues, and limitations

In the below parts, we are listing issues that have been identified but not yet addressed in the proposed firmware release. These issues will be addressed in future release of the firmware. When an issue cannot be fixed, it will be listed as a limitation. MK1 and MK2/MK1.5 having different hardware, there are different known issues depending on the product hardware versions.

### Warning

#### *Common to all ISP/I.ISP*

- Switching off then on the ISP / I.ISP from the back panel too quickly may lead to improper power up. It is recommended to wait about 30s before restarting the unit after a main switch off.
- Online website translation tools such as Google Translate must not be used when configuring the product with the Web User Interface, as this can affect the system names (audio profiles, input names...) inappropriately, leading to misbehavior of the unit and requiring a Factory Reset to recover.
- With some hardware device, fan speed can be set at 50%, that implies fan stop/start loop.
- WebUI is not compliant with Internet Explorer (all versions).

#### *Specific to MK1*

- With V3.5r4 (or onward) firmware version, downgrade to previous versions won't be possible anymore.
- Switching off ISP from back panel if ISP is not in standby/sleep mode could create a very loud plop that can damage your speakers. Make sure to put the unit in standby by pressing the front panel prior switching off the unit in the back panel.
- With some hardware device, "Fault with fan 6" error is fired and never recover.
- With some hardware device, PSU EEPROM is not programmed in production.

#### *Specific to MK2/MK1.5*

- On very rare occasions, decoder can reboot by itself and may not recover the configuration. Content is correctly detected but audio will be muted. Workaround: restart your unit.
- On very rare occasions, FPGA software can get corrupted. Workaround: reinstall the same software version (or install upgrade if available).

## Decoding and audio input limitations

#### *Common to all ISP/I.ISP*

- DTS HD MA equal or higher than 96kHz cannot be upmixed to more than 7.1 with DTS Neural:X and Auro-Matic.

- 6.1 format is not supported and will be played in 5.1 (limitation), feeding the Center Back channel to Surround channels.

#### *Specific to MK1*

- HDMI content with audio sampling frequency above 96kHz may appear on the remote control to be 96kHz.

#### *Specific to MK2/MK1.5*

- Sometimes Dolby legacy stream 5.1 are not upmixed in DTS Neural:X when doing Native → Dolby Surround → DTS Neural:X. Workaround: switch to native and back to DTS Neural:X.

## Decoding and audio input issues

#### *Common to all ISP/I.ISP*

- Glitch can be heard when resuming with Zappiti player.
- In some rare cases, when using Netflix over ARC, we can hear a glitch at Netflix launching or selecting movie.
- In some rare occasions, eARC content is not decoded. Workaround: select an input where BDP is playing content, then switch back to ARC/eARC.

#### *Specific to MK1*

- When playing Auro-3D® content on Theater not having height or top speakers, it is recommended to select Auro-Matic® as "Preferred Upmix".
- When playing DTS:X then switching to "DTS 44.1 kHz 5.1", stream information displayed 7.1.4.
- Sometimes, HDMI card (7+2 version) crash when switching from Full HD to 4K.
- Mute can be heard on play/pause with "Dolby Digital 48 kHz 5.1" (DTS:X decoder only).
- When playing Dolby TrueHD 5.1 or Atmos, upmix StereoDownmix there is no LFE (Dolby decoder only).

#### *Specific to MK2/MK1.5*

- When playing Auro-3D® 13.1 or 11.1 (7+4) content, it is recommended to select Auro-Matic has "Preferred Upmix".
- In rare occasions, when playing Dolby Atmos content, audio can be jerky.
- When playing PCM 7.1 content, upmix DTS Neural:X has no effect.
- When playing PCM 192, 176.4 and 88.2 kHz, content is not decoded after restart. Workaround: select another input whose playing content and switch back to PCM content.
- When playing DTS ES-Discrete content, Auro-Matic Upmix has no effect.
- When playing DTS ES-Discrete or DTS ES-Matrix content changing Preferred Upmix can lead to no audio.
- Dialog Normalization is not working on Dolby TrueHD.
- DRC LFE Downmix is not working on Dolby Digital Plus.
- Sometime 88.2 kHz content is not decoded.
- Playback of some PureAudio Bluray with 24/192 content (DTS HD Master 192 Quadrio 4.0) will always play with Right Surround and LFE missing.

## Audio output issues

#### *Common to all ISP/I.ISP*

- With Digout, plop can be heard during initialisation phase.
- Small plop can be heard at sleep on/off transition.
- Limitation for the sub-theater: cannot allow speaker to have different signal in different sub-theaters of the same Theater.
- Small mute heard when changing Lipsync, Loudness, CinemaEq parameters.



- Child zone definition is now possible as sub-zone of a Theater (with Mono, Stereo Left, Stereo Right and SUB signals selection). Limitation: not possible to use different signal in different child zone.
- Changing from SphereAudio preset to Main Theater will cause plop on speakers.
- There is delay between Theater, Zone, Zone2, Downmix.

#### *Specific to MK1*

- If DTS Neural:X is selected as "Preferred Upmix" and your Theater Speaker layout is 6.1.0.0 or 6.0.0.0 you will not be able to play Auro-3D® content.
- Auro-3D 9.1 or 11.1 content cannot be upmixed to 13.1 (no LB/RB channel).
- Not the same output level for DTS Neural:X vs other surround modes when playing PCM 2.0, 5.1 and 7.1.
- With configurations that supports Wide speakers and 4 Ceilings speakers such as 9.1.0.4, there is a wrong gain set for the routing of the LMT/RMT to LFT/RFT/LBT/RBT channels. It is right now unity gain while it should be 6dB lower.

#### *Specific to MK1.5/MK2*

- Buzz can be heard on speakers Center, Left and Right Surround when selecting a Stereo X Analog input after having played PCM 5.1 or 7.1 over HDMI. Workaround: restart your unit.

## Dirac Live Bass Control

- It not possible to perform Dirac on Child Zone with 2 SUB.

## User interface issues

### *Common to all ISP/I.ISP*

- In the Web Remote Control, for a preset including several zones, the Zone area displayed in the right panel is always set to show the first zone available in the preset when doing a refresh or switching Tab.
- Select arrangement is not the same between Dirac Live (Tightly focused imaging/Focused imaging/Wide imaging) and StormAudio (Chair/Sofa/Auditorium).
- Configurator viewer does not handle configuration with Phantom Center and Theatre without SUB. Calling viewer after Theater creation does not show all information.
- Configurator viewer does not correctly handle configuration with Replicated or Multiways speakers. Calling viewer after Theater creation does not show all information.
- In EQ page, crossover filters and BM have no effect on graph.
- Speakers' Name and Abbreviation can be different depending on the page shown, such as Lsr/Rsr are sometime shown as Lb/Rb, Surround Rear being equivalent to Back.
- When OSD is ON and when playing Dolby Vision content, text message on screen is degraded (limitation).
- In the Copy to EQ dropdown list, wrong channel number displayed if remap has been used. This does not impact "copy to" feature.
- Meter to ms conversion doesn't work well. Delay vs distance being relative, we are using an internal distance as reference. Changing the delay (in ms) may lead to out of range distance after conversion back to meter.
- Never use more than one browser WebUI instance on the same product in installer or expert mode at the same time (limitation).
- Never use more than one browser WebUI instance on the same product in user mode at the same time, as it can display discrepancies with the real parameters applied.
- Triggers delay scheduling at wakeup does not correspond to Inputs configuration settings.
- Preferred Upmix stays on "Input" preference even when "Preset" is changed.
- Loudness and CinemaEQ are still available and settable in remotes but have no audio effect (Control4, Creston, Savant, RTI, iRule).



- When user calls Deep Standby feature via Front Panel, led stay Green.
- Wrong Video Input information can be displayed in monitoring page.
- In Dirac Live® tool, symbol characters are not allowed otherwise export will fail.

*Specific to MK2/MK1.5*

- In page System, during initialization, model shown can be ISP Elite (MK1) instead of ISP MK2.
- Model ISP Elite instead of ISP MK2 is sent by TCP/IP and into EDID Product Name.

# Firmware release historic

You will find below former firmware revision Release Notes summary.

## FW4.0r1 (20200416)

### Changes from 4.0r1 to 4.0r1

- Fixed a bug where Clicking on Save Profile while editing a profile would quit the Edit mode.
- Fixed a bug with Roon where Source Selection would not work after a restart of the Roon Core Software.
- Fixed a bug on MK1 where x.1.2f theater had no sound with legacy streams in Native mode.
- Fixed a bug on MK2 where Dolby legacy 5.1 stream would play as 7.1.

### New features and enhancements of 4.0r0

#### SYSTEM CONTROL

- Bass Management:
  - New filters type has been added (BT 12, BT 24, BT 48, LR 36, LR48).
  - Bass are now managed per speaker, and not per signal.
  - Bass management can handle up to 32 speakers.
  - Bass management is compatible with Dirac Live Bass Control.
  - Fully operational on Child Theater.
- Speaker Configurator:
  - A new layer per layer configurator has been added. It allows to configure a Theater without going through a big list of possible configurations.
  - It is possible to specify whether each speaker is a multiway speaker, a replicated speaker, or even a replicated multiway.
- Inputs:
  - ROON main audio in has been added. Roon ready certification is ongoing.
  - Stereo 5+1 main audio in has been added.
  - XLR In main audio in has been added and can be used as a Zone 2 Audio In. XLR In comes as an alternative to RCA4 In.
- Monitoring:
  - Warning and error message improvement.
  - Vumeter has been reworked to handle up to 24 input channels.
- Save:
  - Modifications are now automatically saved (except on Speakers and System page).
- System:
  - Support: Main Audio Board is now available in the main firmware, no specific external diagnostic firmware is needed.
  - It's now possible for Theaters and Audio Zones to recall an adjustable Default Volume Level at unit power up, with the mode turned to ON.

#### AUDIO FORMATS & SPEAKER CONFIGURATION

- New decoder (MK2/MK1.5 product):
  - No more long switching time between codecs or surround.
  - Up to 24 channel support in Dolby Atmos mode. 13.1.10 configurations are now possible.
  - Compatible with upcoming DTS:X Pro and IMAX Enhanced.

#### DIRAC LIVE BASS CONTROL

- Support of Dirac Live Bass Control add on module has been added, free of charge for StormAudio customers, including for MK1 units' owners.

#### HDMI

- On Screen Display feature is now available (16:9 screen, 21:9 screen, OFF).
- It's now possible to control HDMI audio outputs (ON/OFF).
- HDMI AUX output fully operational.
- Audio stream detection issue (AppleTV+) is now fixed.
- HBR audio extraction issue is now fixed.

#### TCP/IP API

- Add "up / down" commands for Zones volume control.
- IMAX Mode command has been added (preparation for IMAX Enhanced future activation).

#### REMOVED FEATURE

- Monitoring: Vertical limiters bar information has been removed.
- SphereAudio has no effect (if SphereAudio is used, content will be played as Stereo Audio Zone). This is a temporary regression that will be addressed in a future firmware release.

## FW3.5r7 (20191205)

### New features and enhancements

#### SYSTEM & CONTROL

- New upgrade scheme for audio decoder
- Support of new flash ID for W25q64 (J serie)
- Front panel
  - Fix issue with display settings lost at power down

#### HDMI

- HMC82 (7+2 eARC)
  - Fix issue with eARC/ARC audio extraction,
  - Fix HBR audio extraction issue affecting Apple TV Atmos enabled app (Netflix, AppleTV+)

## FW3.5r3 (20190726)

### New features and enhancements

#### SYSTEM & CONTROL

- WebUI
  - Copy to EQ : fix crossover copy issue with EDGE browser
- TCP/IP API
  - Zone volume up and down commands added

#### HDMI

- HSR82P
  - Fix audio stream detection issue

## FW 3.5r2 (20190620)

### New features and enhancements

#### SYSTEM & CONTROL



- TCP/IP API
  - "Proc state" improvement.
- General bug fixes

## FW 3.5r1 (20190415)

### New features and enhancements

#### SYSTEM & CONTROL

- WebUI
  - EQ creation and visualisation
    - Filter frequency response view.
    - Combined filters frequency response view.
    - EQ bank per channel has been increased from 10 to 20.
  - Zone2
    - OPTICAL (PCM only) / COAX (PCM only) / Stereo Analog input can be used has Zone2 audio in.
    - Zone2 audio is displayed in VuMeter.
  - External generator is available for HDMI / OPTICAL / COAX / Stereo Analog.
  - Deep/Standby Network is configurable.
  - Download logs include SQL configuration (only for support).
  - Monitoring unit "sleep" status event added.
  - Input, audio in "eARC" has been replace by "ARC/eARC".
- Dirac Live DLCT 2.x:
  - Management of Dolby Enabled Speakers.
- Room EQ Wizard
  - EQ Filters can be exported from REW, then imported to ISP.
- TCP/IP API
  - Zone2 control command added.

#### HDMI

- HSR72-Q new software
  - Hot Plug Event and authentication improvement.
  - AppleTV improvement.
  - AppleTV switching to Oppo UDP203 improvement.
- New HMC82 board control
  - ARC and eARC compatible.
  - Dolby Vision, Standard and Low Latency pass through.

### Removed features

#### SYSTEM & CONTROL

- WebUI
  - Loudness and CinemaEQ

## FW 3.4r4 (20190326)

### New features and enhancements

#### SYSTEM & CONTROL

- Dirac Live DLCT 2.x
  - communication stability improvement,
  - Real-time noise generator impossible level adjustment issue addressed,
- Correction of Volume Zone command, in link to TCP/IP and Control Systems (RTI, Crestron).

## FW 3.4r2 (20181219)

### New features and enhancements

#### SYSTEM & CONTROL

- Dirac Live DLCT 2.0 is now available and compatible with ISP/I.ISP. Firmware is still compliant and compatible with Dirac Live for StormAudio 1.0.
- Dirac Live tools can be used with Safari browser (macOS X) running the WebUI.

#### AUDIO FORMATS & SPEAKERS CONFIGURATION

- Improvement of Dolby Atmos detection when played on AppleTV and Xbox.

#### HDMI

- HDMI output drive strength value can be changed (only for support).
- Zappiti media box interoperability improvement.

## FW 3.4r1 (20181009)

### New features and enhancements

#### SYSTEM & CONTROL

- Front panel:
  - New GUI with better readability.
  - Allows for restoring "installer" and "expert" user/password.
- WebUI:
  - Monitor HDMI output 1 and 2 states.
  - Monitor back fan fault.
  - VuMeter and Console are now working over Domotz and remote tunnel.
  - Hardware System info page has been reworked.
  - Only ASCII characters are handled in the editable area.
- New PSU is now detected and managed.
- At wake-up, we force back fan speed at 50% during 1min in order to detect fan failure.

#### HDMI

- Improved EDID handshaking robustness (AppleTV, SONY projector, INNEOS Optical Fiber...) for faster source and resolution change.

## FW 3.4r0 (20180817)

### New features and enhancements

#### SYSTEM & CONTROL

- IR remote control handling through back panel connection. WARNING: "IR IN" is always bottom connector and "IR OUT" is always top connector, whichever silkscreen used.
- 16ch RCA board option can be used as alternate or XLR16 replicate (StormAudio ISP range).
- 16ch AES/EBU Input can now be processed by the decoder for upmixing when in 7.1 or 5.1 mode.
- 16ch AES/EBU Input with Auro-3D encoded 5.1 or 7.1 PCM streams is now detected and decoded.
- XLR 4 board option is now supported.
- Preferred Upmix is now assignable per Input.
- Limiters are now adjustable (level and enable/disable) on a per speaker basis in Speakers page.
- WebUI Improvement (pop-up, screen resolution) to better match with various display resolution.
- Home/rack mode for I.ISP (change fan regulation law) for quieter operation in home mode.
- Volume Level reference (set and recall) for the noise generator in Speakers page.

#### AUDIO FORMATS & SPEAKERS CONFIGURATION

- Speakers Layout expansion to support 9.1.5.6 layout.
- Phantom Center feature is now available for any Speakers layout.
- Sub Theater definition is now possible as sub-zone / child zone of a Theater (with Mono, Stereo Left, Stereo Right and SUB signals selection). Limitation: not possible to use different signal in different child zone.

## FW 3.3r2 (20180606)

### New features and enhancements

#### SYSTEM & CONTROL

- Custom Bass Management has been renamed to "Expert" Bass Management.
- Parameters changed in Edit Speakers page are now automatically saved when going on EQ page.

#### AUDIO FORMATS & SPEAKERS CONFIGURATION

- PCM upmixed with DTS Neural:X reaches saturation on center and wide channels correction.
- Improvement of PCM 44.1 and 48 kHz transition with play/pause/skip from source.
- Improved phase response of the 2nd order filters used for Multi-Way speakers and Bass Management and of the 4th order filters used in the LARGE AND SUB case for the Bass Management is available.

## FW 3.3r0 (20180410)

### New features and enhancements

#### SYSTEM & CONTROL

- Software upgrade will only update parts of the firmware that are different from the upgrade package used. It is nevertheless possible to force update of all modules (HDMI and audio decoder).
- Export extension of a configuration backup and log files are now \*.7z file and suffixed with date of day (compatibility with \*.dat file is maintained).
- EDID information settings:
  - Manufacturer Plug N Play ID is "IMF"
  - Product Code
  - Serial Number (not being handled properly by HDMI board)
  - Manufacture Week and Year
  - Product Name
  - Manufacturer's Name
- New monitoring panel for Signal informations.
- New monitoring panel for Video In informations.
- New HDMI settings:
  - Possibility to extend HDMI2.0 capability to all inputs.
  - Possibility to change HDMI2.0 speed limit to 450 MHz instead of 600 MHz.
- Dirac possible Timeout issue ("Deadline exceeded") is corrected.

#### AUDIO FORMATS & SPEAKERS CONFIGURATION

- Up to 9.1.6 speakers layout native decoding for Dolby Atmos (16ch discretely-rendered channels).
- Up to 9.1.2 speakers layout native decoding for DTS:X.
- Speakers Layout possibilities have been expanded to support the 16 ch decoding expansion (9.1.0.5, 9.1.1.5, 9.1.4.1, 9.1.4.5, 9.1.5.1, 9.1.5.5).
- Possibility to adjust the delay in the Speakers Configurator with 0.02ms pitch.

## FW 3.2r6 (20180410)

### New features and enhancements

#### SYSTEM & CONTROL

- DRC for Dolby Digital Plus: Is now following DRC requirements.
- Upgrade Support of new decoder Flash memory.

## FW 3.2r5 (20180202)

### New features and enhancements

#### SYSTEM & CONTROL

- SD card Read Only issue has been addressed with a Rescue process using an external USB Flash dongle.

## FW 3.2r4 (20180116)

### New features and enhancements

#### EXTENSION BOARD AND TOOLS

- Use of the microphone connected to the USB port for remote monitoring (StormMonitoring), is now extended with the use of CAT5 UTP extender.

#### AUDIO FORMATS & SPEAKER CONFIGURATIONS

- Auro Immersive VOG signal is played on all available tops speakers if Theater configuration does not contain VOG discrete speakers.
- Improvement of the PCM 48 kHz frequency response from 20 Hz to 22 kHz.
- Digital Input map configuration speakers is not lost anymore.
- I.ISP product, SUB limitation on XLR output has been removed allowing for full 16ch speakers layout selection.
- During configuration, Preview configuration layout has been added in configurator pop-up.
- Generator bug correction when using SphereAudio not bypassed.

#### SYSTEM & CONTROL

- In Edit mode, Improvement of Speaker Configurator "Viewer".
- During configuration, Viewer has been removed from configurator pop-up.
- Invert column has been moved to the right.
- Improvement of Monitoring feedback messages.

## FW 3.2r0 (20171123)

### New features and enhancements

#### AUDIO FORMATS & SPEAKER CONFIGURATIONS

- SphereAudio Cinema Effect has been added.



- Speakers Layout possibilities have been expanded to support Wide speakers for Dolby Atmos and Dolby Surround (true wide only in 9.x.y.2 layout and synthesized wide for other layout 9e.x.y.z).
- Preferred Upmix is now Preset based.
- Output remapping capability has been added.
- Bass Management is now available in two modes: Standard and Custom, offering full flexibility in bass redirection in Custom mode.
- In the Speaker Layout configurator, Surround Height (Auro-3D) and Surround Back Height (DTS:X) are now combined for more clarity.

#### SYSTEM & CONTROL

- Control4 system control driver has been updated with more functions accessible, especially the support of audio zones and audio adjustments.
- A delay function has been added to the Triggers settings (immediate, 1sec, 2sec, 3sec, 4sec, 5sec, 6sec, 7sec and 8sec).
- The general gain per Theater has been increased to 12dB.
- Monitoring page has been added (with VuMeter graphics, power, temperature, fan speed supervision and event log, for ISP, I.ISP and PA).
- Real Time Analyser graphic visualization has been added to the Speakers edition page.
- PA upgrade is now available from ISP or IISP web page.
- PA upgrade web page is now available (in its beta version).
- Preferred upmix is now selectable on front panel.
- Active upmix information is displayed on front panel and on WebUI Remote page.
- New TCP/API command has been added to allow sending text message to client APP.
- The USB upgrade process will not restart in loop.

## FW 3.1r4 (20171005)

### New features and enhancements

#### EXTENSION BOARDS AND TOOLS

- AVB optional board is now fully supported.

#### AUDIO FORMATS & SPEAKER CONFIGURATIONS

- The down firing speaker of a Dolby Enabled Speaker can now be selected as FRONT, SIDE or BACK.

#### SYSTEM & CONTROL

- A Fast Boot Setting is now available. When activated, ISP comes out of standby in a few seconds. Standby Power Consumption is higher when Fast Boot is enabled.

## FW 3.1r0 (20170703)

### New features and enhancements

#### EXTENSION BOARDS AND TOOLS

1. The ISP / I.ISP will now support the Dirac Live™ Room Calibration process for up to 32ch Theaters.
  - A StormAudio specific license of the Dirac Live Room Calibration Tool™ (DLCT) is required to be installed in the laptop to capture via a USB microphone the acoustic response of the room. The DLCT will then create a correction filter design exported via the network to the ISP / I.ISP for Realtime playback.
  - Any ISP / I.ISP will support the Dirac Live™ runtime after this firmware upgrade.



- Dirac Live calibration can be applied to all Theater or Audio Zones, except headphones zones.
  - The DLCT license is part of an Integrator Calibration Kit available for sale, check your distributor for availability and order.
2. A new hardware optional module is now available for the ISP:
- Dual Theater with 16 RCA unbalanced connectivity.

#### AUDIO FORMATS & SPEAKER CONFIGURATIONS

3. The SphereAudio engine powered by Auro®-Headphones™ has been added to the Headphones audio zones via a specific Listening Presets to be defined at the Preset level. There will be 4 binaural SphereAudio Effects available on the Remote Controls: Bypass, Lounge, Home Cinema and Concert.
4. Speakers Layout possibilities have been expanded to support above new features (2.1.0.2m, 3.1.0.2m, 4.1.0.2m, 2.0.0.2m, 3.0.0.2m, 4.0.0.2m).
5. LFE and low frequencies of "Small speakers" signals can now be routed to any "Large" declared speaker of the Base layer, in addition to the Subwoofers.

#### SYSTEM & CONTROL

1. Unit will restart automatically after an unexpected power cut and in the same state it was before the power cut.
2. StormRemote App is available for test for your iPad. Please contact [info@stormaudio.com](mailto:info@stormaudio.com) to request an access with your iPad account email address. TestFlight will need to be installed in the iPad to download and access it.
3. Crestron system control is available (basic and advanced commands).
4. Control4 system control is available (basic commands).

#### PRODUCT CONFIGURATION

6. With the integration of Dirac Live™, we have changed the way to manage the various audio configurations possible within a Theater and an Audio Zone with the creation of Audio Profiles, combining Speakers configuration, Manual Equalization and Dirac Live Filter Design. Audio Profile will replace the "Theater EQ" concept of former firmware revision.
- With this major update, your Theater EQs will be migrated into as many Audio Profiles as you created Theater EQs.
  - You will be able to use this migrated Audio Profiles as basis to run Dirac.
7. To compensate for the headroom required by Manual Equalization and Dirac Live filter design, it is now possible to increase the Digital Gain of all the outputs on a per-theater basis from 0 to 9dB, per 3dB steps.
- It has to be noted that improper use of this adjustment can lead to clipping of the outputs.

## FW 3.0r0 (20170411)

### New features and enhancements

#### AUDIO FORMATS & SPEAKER CONFIGURATIONS

1. The Auro-3D® engine is integrated, supporting decoding and upmixing up to 13.1, in addition to the Atmos and DTS:X engines.
2. Dolby® Atmos decoding and upmixing is expanded to support 7.1.6 speaker configuration.
3. Few configurations without Center channel has been added.
4. Speakers Layout possibilities have been greatly expanded to support above new features.

- (see below the list of supported configurations).

#### SAMPLING RATES

5. Audio formats with sampling rate up to 192kHz are now supported.
6. DTS 96/24 is now supported.

#### PRODUCT CONFIGURATION

7. Improvement of Web-UI Inputs page is making configuration easier.
8. Narrow Band Pink Noise option has been added to the test signal generator for a more accurate speaker level adjustment..
9. Sine frequency test signal is extended down to 10 Hz.
10. The test signal routed to a speaker will be simultaneously routed to the subwoofer channel (according to the Speakers settings) to allow for proper Channel & Subwoofer matching adjustment.
11. The 16ch AES/EBU Digital Input has a modifiable channel mapping and audio sync selection to accommodate specific audio servers output routing.
12. Maximum gain for Tone adjustments available on the Remote Control can be set to 0, 3dB or 6dB in the Settings page.

#### PRODUCT MONITORING

13. Temperature and fan speed are displayed on Front Panel system info page.

#### FIRMWARE INSTALLATION

14. The Firmware Package is now common to ISP and I.ISP.