Manic Moose Sources

S2.32 image (x86)

https://support.bryston.com/old_vps/manicmoose/manicmoose.img.zip

md5sum 17000d536afe7bda247d42c04dea6ac4

S2.44 image (RPi)

BDP-Pi and BDA-3.14

https://support.bryston.com/old_vps/manicmoose_armv7l/manicmoose_S244_arm_pi23.img.zip md5sum 621b2608ccda1a7ba355a3d8e7d2d0bf

S2.44 image (RPi aarch64)

BR-20

https://support.bryston.com/old_vps/manicmoose_armv7l/manicmoose_S244_arm_pi4.img.zip md5sum 6a7130e1acc99c4f76b59f3f7dfb045d

These images require a storage device of atleast 8GB and can be imaged using Etcher.io

MPD Sources

We use several different versions of the MPD between the two firmware revisions. As of March 3 2021 we do not modify MPD and leave them as stock. This archive includes the configuration as to documentation which plug-ins/features are supported.

http://vps96186.vps.ovh.ca/files/mpd_src.tar.gz

Support

http://support.bryston.com/

Contact

For any questions, concerns or requests please feel free to contact Bryston Ltd.

Email

Chris Rice, crice@bryston.com

Phone

1-800-632-8217 1-705-742-5325

Web

http://bryston.com/pages/contact.html